|                  | Approved For Release 2003/08/05 : CIA-RDP82-0945  | Degraph DEIVITA  | \L           |
|------------------|---|--|--------------|
| •                | CLASSIFICATION 3  | 25X1A  | 25X1         |
|                  | CENTRAL INTELLIGENCE AGENCY   | REPORT, NO.  |              |
|                  | INFORMATION REPORT  | CD NO.   |              |
| COUNTRY          | ( USSR (Leningrad ND)   |  | <b>K1A</b>   |
|                  |   | DATE DISTR.  |              |
| SUBJECT          | •   | NO. OF PAGES 2   | •            |
| PLACE<br>ACQUIRE | DETUDN TO CIA IBRARY  | NO. OF ENCLS. 1@   | X1A          |
| DATE OF          | INFO. 25X1X   | SUPPLEMENT TO  | ATA .        |
| OF ITS CONTE     | BY CONTAINS INFORDATION APPECTING THE NATIONAL DEFENDS TO STATES WITHIN THE ELEANING OF THE ESPIONACE ACT SO TO STATES WITHIN THE ELEANING OF THE ESPIONACE ACT SO TO SA, AS AUGURED. ITS TRANSMERSION OF THE ROYALATION RITE IN ANY EMPRISOR TO AN UNADTHORIZED PERSON IS PRO- ANY ROYALOUTION OF THIS FORM IS PROMISTED.                            | *except as noted   | <br>25X1X    |
| SOURCE           |   |  |              |
| 1.,              | Location and installations: See Innex.  |  |              |
|                  | but its 2- extension was probably much crefeet source had recently been drained so the viceable in all weather. The drainage work the 5,000-foot runway with a concrete surfathick, was being extended in April 1949. The ture was first in the ratio of 1:6, later The 1,800-foot concrete taxiway in front of being extended towards the southeast. | at the field was ser-<br>was being continued,<br>ce about 8 inches<br>he concrete mix-<br>in the ratio of 1:2. |              |
| 3.               | of the three destroyed hangars, one had bee reconstructed (dimension: 100 x 135 x 50 fe livered from Germany, 100 x 165 x 35 feet, The two other hangars were scheduled for re-   | et). A hangar de-<br>was being set un.   |              |
| 4。<br>X1X        | The aircraft were fueled with lead gasoline rating 87   | with the octane  |              |
| 5.               | The following navigating and signal equipme   | nt was available:  |              |
|                  | a. Night landing facilities: Boundary light lamps red-white, red obstacle lights, white red boundaries of landing strip.  | hts: reon quartz<br>landing strip,   |              |
|                  | b. Radio station and radar station: he lat the extension of the rurray (see Arnex). Some masts were 10 feet high, the two main high. The DF station in the administration antennas. The Lenthra radio station with 2 antennas 10 feet high and the lajak station  | ones about 90 feet<br>building had rod<br>5 masts and 10 rod   | <b>25</b> X1 |
|                  | ing and transmitting stations to cables about 35 inches underground.  c. "eather stations: In a special buildin   | g and in the ad-   | TIAL .       |
|                  | ministration building. Only the latter was  | in operation.  |              |
|                  |   |  |              |
| STATE            | CLASSIFICATION STATEST  | 2  | 25X1         |

Next Review Date: 2008

- building.
- from the runway to the pumping station; this station had two
- Flying: At least 12 commercial aircraft airived each day from every direction. pproximately the same number took off again. Douglas twin-engine aircraft with radial engines were almost exclusively seen. Large aircraft with dual landing wheels and nose wheel have been observed in increa ing number since mid-1948.

## 25X1A Comment:

25X1

- a. The setting up of a German hangar may be considered confirmed since equipment dismantled at the BURLIU-TETPELHOF Sterfens & Roelle Firm was previously observed at the field.
- b. The utilization of lead fuel appears credible. According to available information, the Goviets use avaiation gasoline with octane ratings of 85 or 86. Of modern installations at this airport, the up-to-date traffic control service previously pointed out. The use of DC-3s (II-2) and of IL-12s as airliners can also be considered confirmed.
- c. The presence of four-engine bombers mentioned in a previous report was not observed. However, the reported expansion of the field, observed since April 1949, may be considered as a partial confirmation of the previous report.
- l Annex: Airport South of LETINGRAD

| 1577  |  |  |
|-------|--|--|
| 1.1.4 |  |  |
|       |  |  |



25X1